

大仁地区 台風18号冠水被害状況調査図 平成26年10月6日



S = 1 : 5 0 0 0

凡 例

- 冠水区域
- 床下浸水区域
- 床上浸水区域

地区名	冠水面積	床上浸水	床下浸水
宗光寺地区	11.17 ha	-	-
白山堂地区	5.21 ha	-	-
神島地区	4.73 ha	-	-
吉田地区	5.23 ha	-	-
合計	26.34 ha	-	-

